



BUILDING AND HOME AUTOMATION SOLUTIONS

ABB-Welcome IP

Release Note Firmware

[Click here for English Release Note](#)

[Klicken Sie hier für die Softwareinformation auf Deutsch](#)

<https://new.abb.com/low-voltage/products/building-automation/product-range/abb-welcome>

We reserve the right to make technical changes or modify the contents of this document without prior notice. ABB shall in no case be liable under, or in connection with, the document towards any person or entity, to which the document has been made available, in view of any damages or losses - irrespective of the legal grounds.

In particular ABB shall in no event be liable for any indirect, consequential or special damages, such as – but not limited to – loss of profit, loss of revenue, loss of earnings, cost of capital or cost connected with an interruption of business. With regard to purchase orders, the agreed particulars shall prevail. © Copyright 2020 ABB. All rights reserved

BUILDING AND HOME AUTOMATION SOLUTIONS

ABB-Welcome IP

Release Note Firmware

Product name	Welcome IP Touch Lite 7
Product type	H8249-1W H8249-1B
Order code	2TMA130051W0010 2TMA130051B0009 2TMA130050W0069 2TMA130050B0069
Latest change	Firmware Update, June 2025

Current Status:

Product Type	Order Code	Website	Firmware
H8249-1W H8249-1B	2TMA130051W0010 2TMA130051B0009 2TMA130050W0069 2TMA130050B0069	Link	Firmware: 1.14

NOTE:

We recommend ensuring that devices are always installed and operating using the latest firmware and software versions. Claims for defects or damages due to the use of software or firmware versions that have not been kept up to date will not be accepted.

FIRMWARE

Product Type	Version	Release Date	Updates and Release Notes
H8249-1	V1.14	June 2025	Updates and Bugfixes: • The surveillance call function in the status bar has been optimized: ○ The system now informs the user if no outdoor station or IP camera is available for surveillance. ○ When multiple outdoor stations or IP cameras are available, closing a warning no longer closes the surveillance window, allowing a smoother switching between devices. • Other minor issues have been fixed.
H8249-1	V1.13	January 2025	New Feature The “Multicast forwarding” default setting now comes pre-enabled, optimizing the performance in big installations. Updates and Bugfixes: • Various bug fixes • Various translation improvements
H8249-1	V1.12	October 2024	New Features: • Group Call: Indoor stations can now be grouped, allowing each group to have a dedicated call button on the outdoor station. • Call forwarding: Door calls can be forwarded to another indoor station if needed. Up to 10 different call forwarding options can be defined, including time profiles. • Custom Call Button Assignment: Physical call buttons on outdoor stations can now be assigned to indoor stations in a user-defined order. To use the new features, the following firmware versions must be installed on the terminals ▪ IP Touch 10 V3.05* (Updated UI*) ▪ IP Touch 7 V3.0* (Updated UI*) ▪ IP Touch 10 V2.53 ▪ IP Touch 7 V2.53 ▪ IP Touch Lite V1.12 ▪ Audio IP V1.25 ▪ Outdoor Station V1.55 ▪ Outdoor Station Mini V1.17 ▪ Smart Access Point V6.59



			Updates and Bug fixes: Indoor stations: Batch function to disable multicast forwarding for indoor stations in private networks.
--	--	--	---

HAUS- UND GEBÄUDEAUTOMATION

ABB-Welcome IP

Freigabemitteilung Firmware

Produktname	Welcome IP Touch Lite 7
Produkttyp	H8249-1W H8249-1B
Bestellnummer	2TMA130051W0010 2TMA130051B0009 2TMA130050W0069 2TMA130050B0069
Aktuelle Version	Firmware Update, Juni 2025

Aktueller Status:

Produkttyp	Bestellnummer	Webseite	Firmware
H8249-1W H8249-1B	2TMA130051W0010 2TMA130051B0009 2TMA130050W0069 2TMA130050B0069	Link	Firmware: 1.14

BEMERKUNG:

Wir empfehlen Ihnen, immer die aktuellste Softwareversion zu installieren. Ansprüche aus Mängeln oder Schäden aufgrund einer nicht aktuell gehaltenen Softwareversion können nicht geltend gemacht werden.

FIRMWARE

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
H8249-1	V1.14	Juni 2025	Updates und Bug fixes: - Die Überwachungsanruffunktion in der Statusleiste wurde optimiert: - Das System informiert den Benutzer nun, wenn keine Außenstation oder IP-Kamera für die Überwachung verfügbar ist. - Wenn mehrere Außenstationen oder IP-Kameras verfügbar sind, wird beim Schließen einer Warnmeldung das Überwachungsfenster nicht mehr geschlossen, wodurch ein flüssigerer Wechsel zwischen den Geräten möglich ist. - Weitere kleinere Probleme wurden behoben.
H8249-1	V1.13	Januar 2025	Neue Funktion: Die Standardeinstellung "Multicast-Weiterleitung" ist jetzt standardmäßig aktiviert, was die Leistung in großen Installationen optimiert.
H8249-1	V1.12	Oktober 2024	Neue Funktionen: - Gruppenruf: Innenstationen können zu Rufgruppen zusammengefasst werden. Jeder Rufgruppe kann eine eigene Ruftaste an der Außenstation zugeordnet werden. - Rufumleitung: Der Türruf kann bei Bedarf an eine andere Innenstation weitergeleitet werden. Es können 10 verschiedene Rufumleitungen inkl. Zeitprofil definiert werden. - Die Ruftasten der Außenstationen mit physikalischen Tasten können nun in einer benutzerdefinierten Reihenfolge den Innenstationen zugeordnet werden. Um die neuen Funktionen nutzen zu können, muss folgende FW-Version auf den Feldgeräten installiert sein: - IP Touch 10 V3.05* (Neue Bedienoberfläche*) - IP Touch 7 V3.0* (Neue Bedienoberfläche*) - IP Touch 10 V2.53 - IP Touch 7 V2.53 - IP Touch Lite V1.12 - Außenstation V1.55 - Außenstation Mini V1.17 - Smart Access Point V6.59 Updates und Bug fixes: Innenstationen: Batch-Funktion zur Deaktivierung der Multicast-Weiterleitung für Innenstationen in privaten Netzwerken.