



62861

NL

Inspectiebocht RVS-galva Ø150/100 90°

FR

Coude d'inspection inox-galva Ø150/100 90°

EN

Inspection elbow SST-galva Ø150/100 90°

DE

Bogen galva-Edelstahl Ø150/100 90°, mit Inspektionsöffnung

Subject to changes. Usage only after written consent of DRU Verwarming B.V.

62861/0