

CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L36588-166-02902002-6
Report Reference E36588-20020920
Date 21-Nov-2023

Issued to: ABB Electrification Sweden AB, Motor Starting & Safety
Motorgrand 20
Vasteras, Vastmanlands lan 721 61
Sweden

This is to certify that representative samples of NLDX - Motor Controllers, Magnetic
See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 60947-4-1, 4th Ed., Issue Date: 2022-05-31, UL 60947-1, Edition 6, Issue Date 2022-05-31

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.

Deborah Jennings-Conner

Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L36588-166-02902002-6
Report Reference E36588-20020920
Date 21-Nov-2023

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
AF1350 or AF1650, may be followed by B, followed by -30, followed by --01, -10, 00, -11, -22, may be followed by -69 or -70.	Magnetic Motor Controllers
AF1350T or AF1650T, followed by -30, followed by -01, -10, -00, -11, -22, may be followed by -91.	Magnetic Motor Controllers
AF1650N8, followed by -30, may be followed by M or R, followed by -01, -10, -00, -11, -22, followed by -69 or -70.	Magnetic Motor Controllers
VM1650H	Magnetic Motor Controllers

Deborah Jennings-Conner

Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L36588-466-02902002-6
Report Reference E36588-20020920
Date 21-Nov-2023

Issued to: ABB Electrification Sweden AB, Motor Starting & Safety
Motorgrand 20
Vasteras, Vastmanlands lan 721 61
Sweden

This is to certify that representative samples of NLDX7 - Motor Controllers, Magnetic Certified for Canada
See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.


Standard(s) for Safety: CSA C22.2 No. 60947-4-1:22, Edition 3, Issue Date 2022-05-31, CSA C22.2 No. 60947-1:22, 3rd Ed., Issue Date: 2022-5-31

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.


Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number UL-CA-L36588-466-02902002-6
Report Reference E36588-20020920
Date 21-Nov-2023

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
AF1350 or AF1650, may be followed by B, followed by -30, followed by --01, -10, 00, -11, -22, may be followed by -69 or -70.	Magnetic Motor Controllers
AF1350T or AF1650T, followed by -30, followed by -01, -10, -00, -11, -22, may be followed by -91.	Magnetic Motor Controllers
AF1650N8, followed by -30, may be followed by M or R, followed by -01, -10, -00, -11, -22, followed by -69 or -70.	Magnetic Motor Controllers
VM1650H	Magnetic Motor Controllers

Deborah Jennings-Conner

Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

