



BUILDING AND HOME AUTOMATION SOLUTIONS

# ABB-Welcome IP

## Release Note Firmware

[Click here for English Release Note](#)

[Klicken Sie hier für die Softwareinformation auf Deutsch](#)

<https://new.abb.com/low-voltage/products/building-automation/product-range/abb-welcome>

We reserve the right to make technical changes or modify the contents of this document without prior notice. ABB shall in no case be liable under, or in connection with, the document towards any person or entity, to which the document has been made available, in view of any damages or losses - irrespective of the legal grounds.

In particular ABB shall in no event be liable for any indirect, consequential or special damages, such as – but not limited to – loss of profit, loss of revenue, loss of earnings, cost of capital or cost connected with an interruption of business. With regard to purchase orders, the agreed particulars shall prevail. © Copyright 2020 ABB. All rights reserved



BUILDING AND HOME AUTOMATION SOLUTIONS

# ABB-Welcome IP

## Release Note Firmware

|               |                                                                                                |
|---------------|------------------------------------------------------------------------------------------------|
| Product name  | Welcome IP Outdoor Station (IPpush button, IPkeypad, IPtouch 5) --- HGO05/HSM53 (View Website) |
| Product type  | H81381T , H81381P, H81381K                                                                     |
| Order code    | 2TMA130010X0001                                                                                |
|               | 2TMA130010X0002                                                                                |
|               | 2TMA130010X0003                                                                                |
|               | 2TMA130010X0009                                                                                |
|               | 2TMA130010W0021                                                                                |
|               | 2TMA130010W0025                                                                                |
|               | 2TMA130010W0029                                                                                |
|               | 2TMA130010W0013                                                                                |
|               | 2TMA130010W0033                                                                                |
|               | 2TMA130010W0037                                                                                |
|               | 2TMA130010X0019                                                                                |
|               | 2TMA130010X0020                                                                                |
|               | 2TMA130010X0021                                                                                |
|               | 2TMA130010X0027                                                                                |
|               | 2TMA130010X0043                                                                                |
|               | 2TMA130010X0044                                                                                |
|               | 2TMA130010W0023                                                                                |
|               | 2TMA130010W0027                                                                                |
|               | 2TMA130010W0031                                                                                |
|               | 2TMA130010W0017                                                                                |
|               | 2TMA130010W0035                                                                                |
|               | 2TMA130010W0039                                                                                |
| Latest change | Firmware Update, October 2023                                                                  |

Current Status:

| Product Type | Order Code                                                                                                                                                                                                                                                                                                                                                                                                                     | Website              | Firmware       |
|--------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------|
| HGO05/HSM53  | 2TMA130010X0001<br>2TMA130010X0002<br>2TMA130010X0003<br>2TMA130010X0009<br>2TMA130010W0021<br>2TMA130010W0025<br>2TMA130010W0029<br>2TMA130010W0013<br>2TMA130010W0033<br>2TMA130010W0037<br>2TMA130010X0019<br>2TMA130010X0020<br>2TMA130010X0021<br>2TMA130010X0027<br>2TMA130010X0043<br>2TMA130010X0044<br>2TMA130010W0023<br>2TMA130010W0027<br>2TMA130010W0031<br>2TMA130010W0017<br>2TMA130010W0035<br>2TMA130010W0039 | <a href="#">Link</a> | Firmware: 1.47 |

NOTE:

We recommend ensuring that devices are always installed and operating using the latest firmware and software versions. Claims for defects or damages due to the use of software or firmware versions that have not been kept up to date will not be accepted.

FIRMWARE

| Product Type | Version | Release Date | Updates and Release Notes                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
|--------------|---------|--------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| HGO05/HSM53  | V1.47   | October 2023 | <p>New Features:</p> <ul style="list-style-type: none"><li>• Door Entry Local API for Welcome IP &amp; AccessControl: The Door Entry Local API can be accessed directly from the local network. For more information please visit: <a href="https://developer.eu.mybuildings.abb.com/documentation">https://developer.eu.mybuildings.abb.com/documentation</a></li><li>• Door Entry Cloud API for Welcome IP &amp; AccessControl: The Door Entry Cloud API can be accessed directly from the ABB Cloud. For more information please visit: <a href="https://developer.eu.mybuildings.abb.com/documentation">https://developer.eu.mybuildings.abb.com/documentation</a></li><li>• Built-in SIP server: The Smart Access Point Pro can now act as a SIP server, supporting 3rd party SIP client devices and applications.</li><li>• SIP Client feature for outdoor stations: The outdoor stations can also be integrated into an IP-PBX as a SIP client. The settings can be enabled in the Smart Access Point.</li></ul> <p>Requirements: Outdoor station firmware ver: V1.47<br/>Requirements: Smart Access Point: V6.38</p> <p>UI improvements:</p> <ul style="list-style-type: none"><li>• For 1,2 and 3 tenants, it will be automatically added a ring icon next to the tenants name list to facilitate visitors to interact with the touch screen.</li></ul> <p>Updates and bug fixes:</p> <ul style="list-style-type: none"><li>• Various translation improvements</li><li>• Cyber security improvements</li></ul> |

---

|             |       |                |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
|-------------|-------|----------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| HGO05/HSM53 | V1.31 | September 2022 | <p>New Features and UI improvements:</p> <ul style="list-style-type: none"><li>• Editable Font size for Residents list</li><li>• New image for the 'Password/QRCode Unlock' icon on the main page</li><li>• New order of personal details on the Resident List: the surname will be set before the the given name for all language</li><li>• Automised call feature: a call will be automatically triggered when a specific contact on the Resident List is selected, after a 3 second pulsating count down</li><li>• Newly added 'Stop Call' button: the button will allow to terminate the call during the 3 seconds count down when the automised call is triggered</li></ul> <p>Bugfixes:</p> <ul style="list-style-type: none"><li>• Various bugfixes</li></ul> |
|-------------|-------|----------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

---



HAUS- UND GEBÄUDEAUTOMATION

# ABB-Welcome IP

## Freigabemitteilung Firmware

|                  |                                                                                                |
|------------------|------------------------------------------------------------------------------------------------|
| Produktname      | Welcome IP Outdoor Station (IPpush button, IPkeypad, IPtouch 5) --- HGO05/HSM53 (View Website) |
| Produkttyp       | H81381T , H81381P, H81381K                                                                     |
| Bestellnummer    | 2TMA130010X0001                                                                                |
|                  | 2TMA130010X0002                                                                                |
|                  | 2TMA130010X0003                                                                                |
|                  | 2TMA130010X0009                                                                                |
|                  | 2TMA130010W0021                                                                                |
|                  | 2TMA130010W0025                                                                                |
|                  | 2TMA130010W0029                                                                                |
|                  | 2TMA130010W0013                                                                                |
|                  | 2TMA130010W0033                                                                                |
|                  | 2TMA130010W0037                                                                                |
|                  | 2TMA130010X0019                                                                                |
|                  | 2TMA130010X0020                                                                                |
|                  | 2TMA130010X0021                                                                                |
|                  | 2TMA130010X0027                                                                                |
|                  | 2TMA130010X0043                                                                                |
|                  | 2TMA130010X0044                                                                                |
|                  | 2TMA130010W0023                                                                                |
|                  | 2TMA130010W0027                                                                                |
|                  | 2TMA130010W0031                                                                                |
|                  | 2TMA130010W0017                                                                                |
|                  | 2TMA130010W0035                                                                                |
|                  | 2TMA130010W0039                                                                                |
| Aktuelle Version | Firmware Update, October 2023                                                                  |

Aktueller Status:

| Produkttyp  | Bestellnummer                                                                                                                                                                                                                                                                                                                                                                                                                  | Webseite             | Firmware       |
|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------|
| HGO05/HSM53 | 2TMA130010X0001<br>2TMA130010X0002<br>2TMA130010X0003<br>2TMA130010X0009<br>2TMA130010W0021<br>2TMA130010W0025<br>2TMA130010W0029<br>2TMA130010W0013<br>2TMA130010W0033<br>2TMA130010W0037<br>2TMA130010X0019<br>2TMA130010X0020<br>2TMA130010X0021<br>2TMA130010X0027<br>2TMA130010X0043<br>2TMA130010X0044<br>2TMA130010W0023<br>2TMA130010W0027<br>2TMA130010W0031<br>2TMA130010W0017<br>2TMA130010W0035<br>2TMA130010W0039 | <a href="#">Link</a> | Firmware: 1.47 |

**BEMERKUNG:**

Wir empfehlen Ihnen, immer die aktuellste Softwareversion zu installieren. Ansprüche aus Mängeln oder Schäden aufgrund einer nicht aktuell gehaltenen Softwareversion können nicht geltend gemacht werden.

**FIRMWARE**

| Produkttyp  | Version | Erscheinungsdatum | Updates und Release Notes                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
|-------------|---------|-------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| HGO05/HSM53 | V1.47   | September 2022    | <p>Neue Funktionen:</p> <ul style="list-style-type: none"><li>• Door Entry Local API für Welcome IP &amp; AccessControl: Die Door Entry Local API kann direkt aus dem lokalen Netzwerk angesprochen werden. Weitere Informationen unter: <a href="https://developer.eu.mybuildings.abb.com/documentation">https://developer.eu.mybuildings.abb.com/documentation</a></li><li>• Door Entry Cloud API für Welcome IP &amp; AccessControl: Die Door Entry Cloud API kann direkt aus der ABB Cloud angesprochen werden. Weitere Informationen unter: <a href="https://developer.eu.mybuildings.abb.com/documentation">https://developer.eu.mybuildings.abb.com/documentation</a></li><li>• Integrierter SIP Server: Der Smart Access Point Pro kann jetzt als SIP Server fungieren und unterstützt SIP Client Geräte und Anwendungen von Drittanbietern.</li><li>• Aussenstation als SIP-Client: Die Aussenstationen können nun als SIP-Client in eine IP-Telefonanlage (SIP-Server) eingebunden werden. Die Einstellungen können im Smart Access Point aktiviert werden.</li></ul> <p>Voraussetzungen: Außenstation Firmware: V1.47<br/>Voraussetzungen: Smart Access Point Pro Firmware: V6.38</p> <p>UI-Verbesserungen:</p> <ul style="list-style-type: none"><li>• Bei 1, 2 und 3 Mietern wird automatisch ein Ringsymbol neben der Liste der Mieternamen hinzugefügt, um Besuchern die Interaktion mit dem Touchscreen zu erleichtern.</li></ul> |

|             |       |                |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
|-------------|-------|----------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|             |       |                | Updates und Fehlerbehebungen: <ul style="list-style-type: none"> <li>• Diverse Übersetzungsverbesserungen</li> <li>• Cyber Security Verbesserungen</li> </ul>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| HGO05/HSM53 | V1.31 | September 2022 | <ul style="list-style-type: none"> <li>• Neue Funktionen und UI-Verbesserungen:               <ul style="list-style-type: none"> <li>○ Editierbare Schriftgröße für die Bewohnerliste</li> <li>○ Neues Bild für das Symbol "Passwort/QRCode entsperren" auf der Hauptseite</li> <li>○ Neue Reihenfolge der persönlichen Angaben in der Einwohnerliste: Der Nachname wird in allen Sprachen vor dem Vornamen angezeigt</li> <li>○ Automatische Anruffunktion: ein Anruf wird automatisch ausgelöst, wenn ein bestimmter Kontakt in der Bewohnerliste ausgewählt wird, nach einem pulsierenden Countdown von 3 Sekunden</li> <li>○ Neu hinzugefügte Schaltfläche "Anruf stoppen": Die Schaltfläche ermöglicht es, den Anruf während des 3-Sekunden-Countdowns zu beenden, wenn der automatische Anruf ausgelöst wird.</li> </ul> </li> <li>• Fehlerbehebungen:               <ul style="list-style-type: none"> <li>○ Verschiedene Fehlerkorrekturen</li> </ul> </li> </ul> |