



BUILDING AND HOME AUTOMATION SOLUTIONS

ABB-Welcome IP

Release Note Firmware

[Click here for English Release Note](#)

[Klicken Sie hier für die Softwareinformation auf Deutsch](#)

<https://new.abb.com/low-voltage/products/building-automation/product-range/abb-welcome>

We reserve the right to make technical changes or modify the contents of this document without prior notice. ABB shall in no case be liable under, or in connection with, the document towards any person or entity, to which the document has been made available, in view of any damages or losses - irrespective of the legal grounds.

In particular ABB shall in no event be liable for any indirect, consequential or special damages, such as – but not limited to – loss of profit, loss of revenue, loss of earnings, cost of capital or cost connected with an interruption of business. With regard to purchase orders, the agreed particulars shall prevail. © Copyright 2020 ABB. All rights reserved

BUILDING AND HOME AUTOMATION SOLUTIONS

ABB-Welcome IP

Release Note Firmware

Product name Guard unit

Product type H8303

Order code 2TMA130160W0018
2TMA130160W0022

Latest change Firmware Update, June 2024

Current Status:

Product Type	Order Code	Website	Firmware
H8303	2TMA130160W0018 2TMA130160W0022	Link	Firmware: 1.54

NOTE:

We recommend ensuring that devices are always installed and operating using the latest firmware and software versions. Claims for defects or damages due to the use of software or firmware versions that have not been kept up to date will not be accepted.

FIRMWARE

Product Type	Version	Release Date	Updates and Release Notes																																	
H8303	V1.54	June 2024	Preconditions It is required the installation of the following (or later versions) software version: <table><tr><th>Device name</th><th>Abbreviation</th><th>Software version</th></tr><tr><td>SmartAP</td><td>SmartAP</td><td>V6.55</td></tr><tr><td>IP Touch 10</td><td>IP Touch 10</td><td>V2.44</td></tr><tr><td>IP Touch 7</td><td>IP Touch 7</td><td>V2.44</td></tr><tr><td>IP Touch Lite 7</td><td>IP Touch Lite 7</td><td>V1.10</td></tr><tr><td>Outdoor Station</td><td>OS</td><td>V1.53</td></tr><tr><td>Guard Unit</td><td>GU</td><td>V1.54</td></tr><tr><td>IP Actuator</td><td>IPA</td><td>V1.17</td></tr><tr><td>IP Elevator Controller</td><td>IPEC</td><td>V1.15</td></tr><tr><td>Audio IP</td><td>Audio IP</td><td>V1.22</td></tr><tr><td>Mini Video Outdoor Station with IC</td><td>Mini OS (IC)</td><td>V1.13</td></tr></table> New features: Welcome IP System: Simplified Network Structure: All Welcome IP devices can be connected to the same switch. Separate networks are	Device name	Abbreviation	Software version	SmartAP	SmartAP	V6.55	IP Touch 10	IP Touch 10	V2.44	IP Touch 7	IP Touch 7	V2.44	IP Touch Lite 7	IP Touch Lite 7	V1.10	Outdoor Station	OS	V1.53	Guard Unit	GU	V1.54	IP Actuator	IPA	V1.17	IP Elevator Controller	IPEC	V1.15	Audio IP	Audio IP	V1.22	Mini Video Outdoor Station with IC	Mini OS (IC)	V1.13
Device name	Abbreviation	Software version																																		
SmartAP	SmartAP	V6.55																																		
IP Touch 10	IP Touch 10	V2.44																																		
IP Touch 7	IP Touch 7	V2.44																																		
IP Touch Lite 7	IP Touch Lite 7	V1.10																																		
Outdoor Station	OS	V1.53																																		
Guard Unit	GU	V1.54																																		
IP Actuator	IPA	V1.17																																		
IP Elevator Controller	IPEC	V1.15																																		
Audio IP	Audio IP	V1.22																																		
Mini Video Outdoor Station with IC	Mini OS (IC)	V1.13																																		

			therefore no longer necessary. This reduces the installation complexity for the installer and integrator. ○ Welcome IP devices now support dynamic addressing (DHCP), static / customizable or ABB legacy mode (existing algorithm based on the physical address). ○ It is now possible to call the indoor station on floor 0 and negative floors numbers. ○ Bugfixes: ○ Various bugfixes
H8303	V1.40	September 2022	○ New features: ○ Modification of Summer Hours functions. ○ Bugfixes: ○ Various bugfixes

ABB-Welcome IP

Freigabemitteilung Firmware

Produktname	Guard Unit
Produkttyp	H8303
Bestellnummer	2TMA130160W0018
	2TMA130160W0022
Aktuelle Version	Firmware Update, Juni 2024

Aktueller Status:

Produkttyp	Bestellnummer	Webseite	Firmware
H8303	2TMA130160W0018 2TMA130160W0022	Link	Firmware: 1.54

BEMERKUNG:

Wir empfehlen Ihnen, immer die aktuellste Softwareversion zu installieren. Ansprüche aus Mängeln oder Schäden aufgrund einer nicht aktuell gehaltenen Softwareversion können nicht geltend gemacht werden.

FIRMWARE

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes																																	
H8303	V1.54	Juni 2024	Vorbedingungen Die Installation folgender Softwareversionen (oder neuerer Versionen) ist erforderlich: <table><tr><th>Gerätename</th><th>Abkürzung</th><th>Software-Version</th></tr><tr><td>SmartAP</td><td>SmartAP</td><td>V6.55</td></tr><tr><td>IP Touch 10</td><td>IP Touch 10</td><td>V2.44</td></tr><tr><td>IP Touch 7</td><td>IP Touch 7</td><td>V2.44</td></tr><tr><td>IP Touch Lite 7</td><td>IP Touch Lite 7</td><td>V1.10</td></tr><tr><td>Außenstation</td><td>OS</td><td>V1.53</td></tr><tr><td>Concierge Station</td><td>GU</td><td>V1.54</td></tr><tr><td>IP-Aktor</td><td>IPA</td><td>V1.17</td></tr><tr><td>IP-Aufzugsteuerung</td><td>IPEC</td><td>V1.15</td></tr><tr><td>Audio IP</td><td>Audio IP</td><td>V1.22</td></tr><tr><td>Mini-Außenstation Video mit IC</td><td>Mini OS (IC)</td><td>V1.13</td></tr></table> • Neue Funktionen: ○ Vereinfachte Netzwerkstruktur: Alle Welcome IP-Geräte können an denselben Switch (gemeinsames Netzwerk) angeschlossen werden. Getrennte Netzwerke sind daher nicht mehr zwingend erforderlich. Dies reduziert die Installationskomplexität für Installateure und Integratoren.	Gerätename	Abkürzung	Software-Version	SmartAP	SmartAP	V6.55	IP Touch 10	IP Touch 10	V2.44	IP Touch 7	IP Touch 7	V2.44	IP Touch Lite 7	IP Touch Lite 7	V1.10	Außenstation	OS	V1.53	Concierge Station	GU	V1.54	IP-Aktor	IPA	V1.17	IP-Aufzugsteuerung	IPEC	V1.15	Audio IP	Audio IP	V1.22	Mini-Außenstation Video mit IC	Mini OS (IC)	V1.13
Gerätename	Abkürzung	Software-Version																																		
SmartAP	SmartAP	V6.55																																		
IP Touch 10	IP Touch 10	V2.44																																		
IP Touch 7	IP Touch 7	V2.44																																		
IP Touch Lite 7	IP Touch Lite 7	V1.10																																		
Außenstation	OS	V1.53																																		
Concierge Station	GU	V1.54																																		
IP-Aktor	IPA	V1.17																																		
IP-Aufzugsteuerung	IPEC	V1.15																																		
Audio IP	Audio IP	V1.22																																		
Mini-Außenstation Video mit IC	Mini OS (IC)	V1.13																																		

			○ Alle Welcome IP Geräte unterstützen nun dynamische Adressierung (DHCP), statische Adressierung oder den ABB Legacy Modus (ABB Protokoll basierend auf physikalischer Adresse). ○ Auf der Ebene 0 und in den negativen Stockwerken ist es nun möglich, die Innensprechstelle anzuklingeln. • Fehlerbehebungen: ○ Verschiedene Bugfixes
H8303	V1.40	September 2022	○ Neue Funktionen: ○ Modifikation der Sommerzeit-Funktionen. • Fehlerbehebungen: ○ Verschiedene Bugfixes