



Instruction sheet / Инструкция  
Screw terminal / Винтовой клеммник



Poz. 1



	1,5-10	1,5 - 16
S6	3x	3x
S11	6x	5x
S16	9x	7x
S21	12x	9x
S26	15x	11x

Technical data:


$U_N$ : AC 400V / 50/60 Hz

$I_N$ : AC 100A

T: +40 / -5 °C


IP2X

ERC




**ABB**

Instruction sheet / Инструкция  
Screw terminal S26 / Винтовой клеммник S26



Poz. 1



(90A - 100A)

Technical data:


$U_N$ : AC 400V / 50/60 Hz

$I_N$ : AC 100A

T: +40 / -5 °C

IP2X

ERC



**ABB**