







Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservdeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Reservju daļu

XX = AA, AD...

Position

- 1 = E 960 641 XX
- 3 = A 963 226 XX
- 4 = A 962 998 NU
- 5 = A 963 214 XX
- 6 = A 963 427 NU
- 7 = A 962 229 NU
- 8 = A 962 230 NU
- 10 = A 963 432 NU
- 11 = A 962 336 NU
- 13 = A 962 594 NU
- 15 = A 961 810 NU
- 16 = A 962 595 NU
- 18 = A 962 049 XX
- 20 = A 962 050 XX
- 21 = A 961 183 NU
- 23 = A 961 810 NU
- 24 = A 963 342 NU
- 25 = A 961 186 XX
- 26 = A 860 050 XX
- 27 = A 963 651 NU








CERAPLUS
 A 5642 .. A 5644 ..


1210 / A 866 350
 (+ A 865 612)
 Made in Germany





A 5642 ..

A 5644 ..



Ideal Standard
 Roentgenstrasse 9
 54516 Wittlich
 Germany





	P	bar		MAX. 10		5		Q	(3 bar)
	T	°C		MAX. 80		65			l/min
						40			23

