
CYLON® TECHNICAL BULLETIN NO. 539

Issue Date: 15 August 2024

INTEGRA 4.10u9

Summary

Niagara Framework® 4.10u9 now available

Detail

With the migration to Azul, Supervisor stations failed to start upon initial upgrade, with the error "Feature stationAzul not licensed", even though the attribute was accurately in the license viewed through the License Manager.

In 4.10u9, this has been resolved so that Supervisor stations are able to continue the starting process as expected.

Customer Impact

Customers should upgrade their Supervisors to correct this issue at their earliest convenience.