

# INTEGRA 4.14

## Summary

Niagara Framework® 4.14 now available

## Detail

With the migration to Azul, Supervisor stations failed to start upon initial upgrade, with the error "Feature stationAzul not licensed", even though the attribute was accurately in the license viewed through the License Manager.

In 4.14, this has been resolved so that Supervisor stations are able to continue the starting process as expected.

New features added to improve workflows and cybersecurity.

### IT-9000

- DHCP Support on Secondary Port
- 8021x Support

### NEW HTML 5 WEB VIEWS

- Driver Manager Web View
- Niagara Network History Collection Web View
- RDBMS Collection Web View
- On-Call Service Web View
- Weather Service Web View
- Category Service Web View
- Niagara Provisioning Web View
- Standard Building Protocol Web View
  - BACnet Network
  - Lonworks Network
  - Modbus Network

### CONNECTIVITY UPGRADE

- OPC-UA Driver Refresh

### BRICK SCHEMA SUPPORT

- Brick Schema Tag Dictionary

### COMPLIANCE UPGRADES

- BACnet Protocol Revision 16 Update
- ISA 62443-4-1-2018 Certification

### CYBER DEFENCE FEATURES

- Certificate Signing Service
- Multi-tiered Security Dashboard
- SAML Authentication Type Configuration
- Windows Authentication for MS SQL

## HIDDEN-GEM FEATURES

- Workbench supports mouse side buttons 4 and 5
- Stronger Password Protection – Updating non-admin user password requires old password
- Password Update Process
  - Right-click on Authenticator, Use Action: Update password
  - Current password is required before new password is accepted
- Tagging Editor Enhancement
  - Create rules with new tagDictionary Service: NotRule
  - Implied tag rule will imply a tag to indicate when a control point has an alarm extension.
- HTML5 editor enhancement - Added the ability to Sync your navTree to the currently displayed page

## Customer Impact

Customers should upgrade their sites to use these new features at their earliest convenience.