







Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi



Pos.	Part No.
1	A 861 545 AA
2	A 861 371 NU
3	A 861 375 NU
4	A 861 376 NU
5	A 861 549 NU
6	A 861 372 NU
7	A 861 546 NU
8	A 861 169 AA
9	A 861 547 AA
10	A 861 815 AA




IDEAL
Ideal Standard






CERATHERM C100
A 7538 ..

1724 / A 868 970
Made in Germany



Ideal Standard International NV
Corporate Village – Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium
<https://www.idealstandard.com>





P	bar	MAX. 10 0,5	5 1	Q (3 bar)
				I/min
T	°C	MAX. 80	65 55	22 20