



BUILDING AND HOME AUTOMATION SOLUTIONS

Release Note

Busankoppler KNX flex, UP BA/U1.0.11
Busankoppler KNX flex, UP BA/U1.0.1

[Click here for English Release Note](#)

[Klicken Sie hier für die Softwareinformation auf Deutsch](#)

ABB AG-Busch-Jaeger
Freisenbergstraße 2
58513 Lüdenscheid, Germany
Phone: +49 (0)2351 956 1600
Email: info.bje@de.abb.com
www.busch-jaeger.de

We reserve the right to make technical changes or modify the contents of this document without prior notice. ABB shall in no case be liable under, or in connection with, the document towards any person or entity, to which the document has been made available, in view of any damages or losses - irrespective of the legal grounds.

In particular ABB shall in no event be liable for any indirect, consequential or special damages, such as – but not limited to – loss of profit, loss of revenue, loss of earnings, cost of capital or cost connected with an interruption of business. With regard to purchase orders, the agreed particulars shall prevail. © Copyright 2020 ABB. All rights reserved

Release Note

Bus coupling unit KNX flex, FM BA/U1.0.11

Bus coupling unit KNX flex, FM BA/U1.0.1

Bus coupling unit KNX flex, FM BA/U1.0.21

Product name	Bus coupling unit KNX flex, FM
Product type	BA/U1.0.11 BA/U1.0.1 BA/U1.0.21
Order code	2CKA006120A0079, 2CKA006120A0080, 2CKA006120A0081
Latest change	Firmware Update Update 03/2026

Current Status:

Product Type	Order Code	Website	ETS Application	Firmware
BA/U1.0.11	2CKA006120A0079	Link	-	V1.3.2.445 Please use ETS App „ABB Firmware Update 2.0“
BA/U1.0.1	2CKA006120A0080	Link	-	V1.3.2.445 Please use ETS App „ABB Firmware Update 2.0“
BA/U1.0.21	2CKA006120A0081	Link	-	V1.3.2.445 Please use ETS App „ABB Firmware Update 2.0“

NOTE:

We recommend ensuring that devices are always installed and operating using the latest firmware and software versions. Claims for defects or damages due to the use of software or firmware versions that have not been kept up to date will not be accepted.

ETS APPLICATION

Product Type	Version	Release Date	Updates and Release Notes
BA/U1.0.11 BA/U1.0.1 BA/U1.0.21	1.0	- / -	<ul style="list-style-type: none"> Market Introdution

FIRMWARE

Note: For firmware update please use ETS App „ABB/BJE Firmware Update 2.0“

Product Type	Version	Release Date	Updates and Release Notes
BA/U1.0.11 BA/U1.0.1 BA/U1.0.21	1.3.2.445	03/2026	<ul style="list-style-type: none"> Additional functionality for Busch-Watchdog FM Additional functionality Busch-Comfort switch Long key press in the "Send Value/Multiple Operation" function is evaluated. Communication problems between devices in certain bus topologies have been resolved. <p><u>Note:</u> Works only with the exciting Busch-Watchdog and Comfort switch from start of the production date calendar week 9/2026 (See also release notes for Busch-Watchdog and comfort switch) The production date you find on the backside of the device. It's a four-digit-code</p> <div style="border: 1px solid gray; padding: 2px; display: inline-block;">1848</div>
	1.3.1.63	05/2024	<ul style="list-style-type: none"> Improved stability of the Secure implementation Master reset for secure operation no longer required <p>Notes:</p>
	1.3.0.33	02/2024	<ul style="list-style-type: none"> Market Introdution

Softwareinformation

Busankoppler KNX flex, UP BA/U1.0.11

Busankoppler KNX flex, UP BA/U1.0.1

Busankoppler KNX flex, UP BA/U1.0.21

Produktname	Busankoppler KNX flex, UP
Produkttyp	BA/U1.0.11 BA/U1.0.1 BA/U1.0.21
Bestellnummer	2CKA006120A0079, 2CKA006120A0080, 2CKA006120A0081
Aktuelle Version	Firmware Update und ETS Applikationsupdate, 03/2026

Aktueller Status:

Produkttyp	Bestellnummer	Website	ETS Applikation	Firmware
BA/U1.0.11	2CKA006120A0079	Link	-	V1.3.2.445 Bitte nutze die ETS App „BJE Firmware Update 2.0“
BA/U1.0.1	2CKA006120A0080	Link	-	V1.3.2.445 Bitte nutze die ETS App „BJE Firmware Update 2.0“
BA/U1.0.21	2CKA006120A0081	Link	-	V1.3.2.445 Bitte nutze die ETS App „BJE Firmware Update 2.0“

BEMERKUNG:

Wir empfehlen Ihnen, immer die aktuelle Softwareversion zu installieren. Ansprüche aus Mängeln oder Schäden aufgrund einer nicht aktuell gehaltenen Softwareversion können nicht geltend gemacht werden.

ETS APPLIKATION

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
BA/U1.0.11 BA/U1.0.1 BA/U1.0.21	1.0	02/2024	<ul style="list-style-type: none"> Markteinführung

FIRMWARE

Hinweis: Für Firmwareupdate verwenden Sie bitte die ETS App „ABB/BJE Firmware Update 2.0“

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
BA/U1.0.11 BA/U1.0.1 BA/U1.0.21	1.3.2.445	03/2026	<ul style="list-style-type: none"> Firmware für Busch-Wächter, UP implementiert Firmware für Busch-Komfortschalter, UP implementiert Langer Tastendruck in Funktion „Wert senden/Mehrfachbetätigung“ wird ausgewertet. Kommunikationsprobleme zwischen Geräten in bestimmten Bustopologien <p><u>Hinweis:</u> Funktioniert nur mit Busch-Wächter, UP und dem Busch-Komfortschalter ab der Produktionswoche 9/2026 (siehe auch die Release Note zu Busch-Wächter und dem Komfort-Schalter). Das Produktionsdatum befindet sich auf der Geräterückseite. Es besteht aus einem 4-stelligen Code, z.B. 1848 => Jahr 18, Kalenderwoche 48</p>
	1.3.1.63	05/2024	<ul style="list-style-type: none"> Verbesserung der Stabilität der Secure-Implementierung • Masterreset für Secure-Inbetriebnahme entfällt <p>Hinweise: Bei dem Gerät sind maximal 255 Secure-Gruppenadressen nutzbar</p>
	1.3.0.33	02/2024	<ul style="list-style-type: none"> Markteinführung